




Docket No.: 221608US0PCT

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313



RE: Patent No.: 6,915,944
Serial No.: 10/089,067
Issue Date: July 12, 2005
Patentee (s): Minoru TAKAYA, et al.
For: SOLDERING FLUX, SOLDER PASTE, AND
METHOD OF SOLDERING

Certificate
SEP 22 2005
of Correction

SIR:


Attached hereto for filing are the following papers:

**Request for Certificate of Correction
Certificate of Correction (in duplicate)**

Our check in the amount of -0- attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. Further, if these papers are not considered timely filed, then a petition is hereby made under 37 C.F.R. 1.136 for the necessary extension of time. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.


Harris A. Pitlick

Registration No. 38,779

Customer Number

22850

(703) 413-3000 (phone)
(703) 413-2220 (fax)



Docket No.: 221608US0PCT



COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

RE: Patent No.: 6,915,944
Serial No.: 10/089,067
Issue Date: July 12, 2005
Patentee (s): Minoru TAKAYA, et al.
For: SOLDERING FLUX, SOLDER PASTE, AND
METHOD OF SOLDERING

SIR:

Attached hereto for filing are the following papers:

**Request for Certificate of Correction
Certificate of Correction (in duplicate)**

Our check in the amount of -0- attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. Further, if these papers are not considered timely filed, then a petition is hereby made under 37 C.F.R. 1.136 for the necessary extension of time. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.


Harris A. Pitlick
Registration No. 38,779

Customer Number

22850

(703) 413-3000 (phone)
(703) 413-2220 (fax)

DOCKET NO.: 221608US0PCT



IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF:

MINORU TAKAYA ET AL

: EXAMINER: JOHNSON, J.J.

PATENT NO.: 6,915,944

:

ISSUED: JULY 12, 2005

: GROUP ART UNIT: 1725

FOR: SOLDERING FLUX, SOLDER PASTE, AND METHOD OF SOLDERING

REQUEST FOR CERTIFICATE OF CORRECTION

COMMISSIONER OF PATENTS
ALEXANDRIA, VIRGINIA 22313

SIR:

The following is a request for a Certificate of Correction in U.S. Serial Number 10/089,067, now U.S. Patent Number 6,915,944.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implements 35 U.S.C. §254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are attached on Form PTO 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

Harris A. Pitlick
Registration No. 38,779

Customer Number

22850

Telephone: (703) 413-3000
Facsimile: (703) 413-2220

SEP 22 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,915,944
DATED: July 12, 2005
INVENTOR(S): Minoru TAKAYA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, line 8, "100 μ tm" should read --100 μ m--.

Column 12, line 54, "FI G." should read --FIG.--.

Column 15, line 47, "greater, durability" should read --greater durability--.

Column 18, line 61, "TABLE II n" should read --TABLE II--.

Column 23, line 56, "succinic acid" should read --succinic acid--;

Mailing address of sender:

Patent No. 6,915,944

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/02)

No. of add'l copies
@ .30 per page



Page 1 of 1

SEP 22 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,915,944
DATED: July 12, 2005
INVENTOR(S): Minoru TAKAYA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, line 8, "100 μ tm" should read --100 μ m--.

Column 12, line 54, "FI G." should read --FIG.--.

Column 15, line 47, "greater, durability" should read --greater durability--.

Column 18, line 61, "TABLE II n" should read --TABLE II--.

Column 23, line 56, "succinic acid" should read --succinic acid--;

Mailing address of sender:

Patent No. 6,915,944

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/02)

No. of add'l copies
@ .30 per page



Page 1 of 1

SEP 22 2005